

Part 1

Log Part 1 of this maintenance release.
Part 1 of this maintenance release.

A 268628

EXPIRES 3/6/23 OR 1905-1

regulations and except where it ceases to be in
in force until the expiry date or aircraft time in service shown **whichever is the earlier.**

1805-1

☐ IFR ☐ VFR Night ☒ VFR Day

Time 9:00 Date 3/6/22

Operational Category PRIVATE

Place COOTAMUNDOBA

required to be carried out on the aircraft during the period for which this Maintenance Release
ments or conditions imposed under the Civil Aviation Regulations.

Maintenance required

Due at date/
Aircraft TTIS

Complied with, entered & certified
in Log Book or Part 2 of MR

Go to listing: <https://lightaircraftsales.com.au/listings/grumman-aa-1b-trainer/>

58

Date	(1)		Number of Landings	(2) Enter hereunder full details of inspections, minor repairs and maintenance release certificates issued
	Total Airframe Time in Air Hours	Mins		
Brought forward ..				
3/6/22	1805	1		South West Aviation Pty. Ltd. Approval No. 2290
3-Jun-22				
South West Aviation Pty Ltd.				
Approval No 2290				
Job # 12152 refers	A.T.T.S. 1805.1		Prop TSN: 1805.1	
Periodic inspection carried out IAW CAR schedule 5				
Following Airworthiness Directives and special inspections complied with:				
AD/GEN/87a1, AD/AA1/1A, AD/AA1/7, AD/AA1/6, AD/FP/9a1a2, SB-127A, SB-174, SB-195A Part A, and AWPB34-008 Carried out with nil defects noted.				
AD/AA1/2022-03-15, AD/FP/2021-018SR1, AD/FMS/2022-0024, AD/RAD/2021-23-12, AD/RAD/2021-23-13 and AD/SEATS/2021-0137 found N/A.				
Additional work carried out: I.A.W. Grumman American service manual and approved data for modifications				
1. New landing light fitted. 2. New alternator belt fitted. 3. New nav light globe fitted to L/H side. 4. New bearing assy's fitted to nose wheel.				
5. 1 New bearing assy fitted to LH wheel. 6. New air filter element fitted. 7. Prop dynamic balance check and adjustment carried out to below 0.2 IPS.				
8. AWPB34-008 Results				
FOR/STEER N/002 030/032 060/062 E/093 120/122 150/145 S/183 210/213 240/243 W/273 300/304 330/331				
I hereby certify that I have coordinated the whole inspection carried out on VH-ETS S/N: AA1B-0044 for the Periodic inspection schedules and				
found all maintenance has been completed properly and certified IAW CAR 42 ZE. Maintenance Release No. A288628 issued				
For and on behalf of South West Aviation Pty Ltd Approval No 2290. C.T. 561376				
Carry forward ..				

Carry forward ..



54
Corporate Air: Loose Leaf Log Book Entry

Date:- 5 May 2020	VH-ETS S/N AA1B-0044	A/F TTIS:- 1733.1	Landings:-	Job No:- 200131	M/R No. Issued:- A210727	Place:- Goulburn
-----------------------------	-------------------------	----------------------	------------	--------------------	-----------------------------	---------------------

100 hourly inspection carried out IAW logbook statement.

AD/ENG/AA11, CAO 100.5 requirements for clauses 3, 4, 5 and 14, transponder mode A nil operation, transponder removed and serviceable part installed static system and compass swing. AD/AA-1/1A, AD/AA-1/1F, AD/GEN/87A1 C/O seats with nil defects evident.

Magnetic Compass		VH-ETS		E		120		150	
For	N	030	060	090	120	150	180	210	240
Steer	S	210	240	269	297	329			

Engine air intake filter replaced with new part
Vacuum regulator filter replaced with new part
Aircraft inhibited with ACF50
Tail ray light wiring repaired
Static line at Altimeter repaired
Refer attached form 728 for engine condition report.
Aircraft interior and exterior cleaned.
All work carried out IAW Grumman AA1 maintenance manual latest revision

CO-ORDINATORS CERTIFICATION I hereby certify that the whole inspection & maintenance required has been completed and properly certified pursuant to CAR 42ZE

Rob Piggott
For & on behalf of Veeh Aviation Australia Pty Ltd Certificate of Approval 2363

515043 Date 5 May 2020

Carry forward ..

Date:- 28 May 20	Annual inspection C/O seats The following inspections w AD/ENG/AA11, AD/AA-1/1F Airframe, Engine, Electrical LH magneto removed due t Part number on, 4371R, s/r All fuses replaced with circa ACF replaced throughout i Aircraft cleaned and vacuu
----------------------------	---

CO-ORDINATORS CERTI
42ZE

Carry forward ..

52

Date: 27 Nov 17

Brought forward ..

(1)

Total Airframe Time in Air		Months Landed
Hours	Mins	

Corporate Air, Loose Leaf Log Book Entry

Date:-	VH-ETS	AF TTIS:-	Landings:-	Job No:-	MR No. Issued :-	Place:-
27 November 2017	SN AA1B-004	1722.7		172553	A108549	Goulburn

100 hourly inspection carried out (AW logbook statement).

AD/ENG/AA11, CAO 100.5 requirements for transponder, static system and compass swing. AD/AA-11A, AD/AA-117 c/o satis with nil defects evident.

Magnetic Compass		VH-ETS	
For	N	030	060
			E
Slee	002	032	061
			119
For	S	210	240
			W
Slee	180	209	237
			270
			298
			329
YGLB	All radios on	515043	

Upper forward LH and RH engine vibration mounts replaced with new parts.
Lower aft LH and RH engine vibration mounts replaced with new parts.
US com removed, serv part fitted (AW MM and AC43).
Refer attached form 728 for engine condition report.
Aircraft interior and exterior cleaned.
All work carried out (AW Grumman AA1 maintenance manual latest revision)

CO-ORDINATORS CERTIFICATION I hereby certify that the whole inspection & maintenance required has been completed and properly certified pursuant to CAR 42ZE

Rob Piggot 515043 Date 27 November 2017

For & on behalf of Veeh Aviation Australia Pty Ltd Certificate of Approval 2363

Go to listing: <https://lightaircraftsales.com.au/listings/grumman-aa-1b-trainer/>